Chapter 7

VDMS Plotter and Output Variable List

7.1 Using the VDMS Plotter (GUI)

The VDMS package includes a GUI-based Matlab plotting program which provides easy access to approximately 50 commonly referenced plots of the simulation output. After a VDMS simulation has been run, type vdmsp at the Matlab command prompt to launch the VDMS Plotter.

Once started, the top level of the VDMS Plotter appears. Each button on the top level accesses a second level of pre-programmed plots. At this second level each button is associated with a particular plot. Specifically, the available plots are as follows:

Input Plots

Steer Input

Torque Input

Speed Input

Acceleration Input

Simple Driver Model

Path Following

Path Following Error

Ground

Friction Coefficient

Elevation

Lateral Inclination

Longitudinal Pitch

Local Friction

Wheel Paths

Wheel Kinematics

Slip Ratios

Slip Angles

Inclination Angles

Steer Angles

Camber Angles

Loaded Radii

Forward Velocities

Rotational Velocities

Rotational Accelerations

Tire Forces

Normal Loads

Lateral Forces

Longitudinal Forces

Aligning Torques

Spin Axis Torques

Suspension Plots

Suspension Position

Wheel Center Position

Spring Deflection

Wheel Center Velocity

Wheel Center Acceleration

Total Suspension Forces

Spring Forces

Bump/Rebound Stop Forces

Damper Forces

Vehicle Response Plots

State Variables

g-g Plot

CN-Ay Plot

Vehicle Path

Lat. Acc. vs. Steer

Sprung Mass Response Plots

Accelerations

Roll

Pitch

Roll Gradient

CG Height

Differential Plots

Locked/Unlocked

Diff. Torque

Diff. Speed

Diff. Acceleration

Miscellaneous Plots

Aerodynamic Forces

Custom Plots

Custom 1...Custom 9